


1. Please install the driver at first, if it is Windows 10 doesn't require that.



2. Then read the below barcode to COM-port emulation.



@. WN-W-L1001/  
COM-port emulation

3. 3.Read below barcode for USB output.



@. WN-W-L1000/  
USB output